

**Vehicle Technical Inspection Form****NISSAN Patrol GL 3.0 TDi**

VIN	JN1TESY61Z0563416	TRANSMISSION	5 MTA
MAKE	NISSAN	ODOMETER	157,204 KM
MODEL	PATROL	FUEL TYPE	DIESEL
BADGE BODY	GL	ENGINE SIZE	2953
BODY	WAGON	ENGINE CYLINDRES	L4
YEAR OF MANUFACTORY	2010	POWER	158 HP
DRIVE TYPE	4X4	TORQUE	380 Nm
TYRES	235/85 R16	WHEEL RIM	J16 x 6JJ
PLACE OF MANUFACTORY	JAPAN		

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds to the service life of eight years;
- The vehicle paint presents light scratches all over its sides;
- Oil leakage at the turbocharger and possible, at the head of cylinder's gasket;

Remarks:

- There are no tools;
- Winch remote is missing.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 28.06.2017 at 147,210 KM;

Accident history:

- No significant accident records.

Required repairs:

- Clutch kit and flywheel need to be changed;
- Turbo charger-removed
- Alternator removed
- Clutch-brake cylinder removed
- Belt tensioner/V-belt
- Hub-locks front removed
- Acceleration pedal
- Check front /Rear suspension











003303 300066
TEGETA MOTORS

INVOICE No: [REDACTED]

Date / Operator: 23.10.2018

Work order No: EU 3177

CAR	NISSAN
MODEL	NISSAN Patrol
YEAR	2010
Plav. No.	EUMM 035
MILLAGE/KM	157204
VIN	JN1TESY61Z0563416

Work List				Spare Parts List						
#	Work Description	AW	Total Cost EURO.	#	Spare Part Description	Article	QTY	PC	Unit Price EURO.	Total Cost EURO.
1	Flywheel change	7.9	209.35	1	DISC ASSY, CLUTCH	30100-VB008	1	PC	138.56	138.56
2				2	COVER ASSY, CLUTCH	30210-VD200	1	PC	154.12	154.12
3				3	CLUTCH BEARING	30502-69F10	1	PC	20.82	20.82
4				4	FLYWHEEL ASSY	AISIN / FDN-908	1	PC	771.43	771.43
5				5					0	0
6				6					0	0
7				7					0	0
8				8					0	0
9				9					0	0
10				10					0	0
11				11					0	0
12				12					0	0
13				13					0	0
14				14					0	0
15				15					0	0
16				16					0	0
17				17					0	0
18				18					0	0
19				19					0	0
20				20					0	0
21				21					0	0
22				22					0	0
23				23					0	0
24				24					0	0
25				25					0	0
26				26					0	0
27				27					0	0
28				28					0	0
29				29					0	0
			SUM	209.35					SUM	1,084.93

Page 1

Upon the required verifications by the EUMM, the below table shall be mutually accepted by

1. Sum of the Spare Parts and Materials:	1,084.93
2. Sum of the labor:	209.35
3. Total Cost (Labor + Spare parts and Materials)	1,294.28

during service may add some labor and some spare parts that will change labor and spare parts cost.

Vehicle returned to EUMM; full provisional acceptance may follow upon financial verifications by the EUMM FMO.

Customer: EUMM / ID: 2063346988

Tegeta Motors LTD, #5, 12 km, D.Agmashenebeli Alley, ID: 202177205,

Driver: SCHNEIDER Hans-Heinrich

Printed data: 2018-10-23 11:11:11