



Annex 18

MERCEDES Vito Tourer 116 CDI SERVICE SCHEDULE

	Service "A"	Service "B"
	25 000 km	50 000 km
VEHICLE ON FLOOR		
Parking brake travel	N/A	Check/adjust
ABS warning system	N/A	Check/report
Instruments	N/A	Check/report
Switches/controls	N/A	Check/report
Heater blower	N/A	Check/report
Horn	N/A	Check/report
Interior lamps	N/A	Check/report
Front wiper blades	N/A	Check/report
Front screen wash	N/A	Check/adjust
Rear wiper blade	N/A	Check/report
Rear screen wash	N/A	Check/adjust
Headlight wash/wipe	N/A	Check/adjust
Instrument illumination	N/A	Check/report
Direction indicators/hazards	N/A	Check/report
Lighting system	N/A	Check/report
Headlights	N/A	Check/report
Interior/Cabin filter	N/A	Renew
VEHICLE FULLY RAISED		
Engine oil leaks	Check/report	Check/report
Engine oil	Drain/refill	Drain/refill
Engine oil filter	Renew	Renew
Clutch hydraulic system	N/A	Check/report
Clutch clearance	N/A	Check/adjust
Gearbox oil leaks	N/A	Check/report
Gearbox oil	N/A	Check/top-up
Front differential oil leaks	N/A	Check/report
Front differential oil	N/A	Check/top-up
Transfer box oil leaks	N/A	Check/report
Transfer box oil	N/A	Check/top-up
Steering knuckles, drag link, center arm and steering linkage grease	N/A	Lubricate
Steering joints	N/A	Lubricate
Steering rack/box	N/A	Check/report
Steering column couplings	N/A	Check/report
Suspension joints/seals/gaiters	N/A	Check/report
Suspension joints	N/A	Lubricate
Suspension mountings	N/A	Check tightness
Propshaft splines including tightening of bolts	N/A	Check/lubricate
Drive shaft joints/seals/gaiters	N/A	Check/report
Rear differential oil leaks	N/A	Check/report
Rear differential oil	N/A	Check/top-up
Leaf spring mountings	N/A	Check tightness

Exhaust system/mountings	N/A	Check/report
Fuel system leakage	N/A	Check/report
VEHICLE HALF RAISED		
Front brake pads	N/A	Check/report
Rear brake drums/linings	N/A	Check/report
Brake hydraulic system	N/A	Check/report
Tyre condition	N/A	Check/report
Tyre pressures	N/A	Check/adjust
Wheel alignmnet four point	N/A	Check/adjust
Wheels balance	N/A	Balance all
ENGINE BAY OPERATIONS		
Washer bottle(s)	N/A	Check/top-up
Brake fluid reservoir	N/A	Check/top-up
Clutch fluid reservoir	N/A	Check/top-up
Power steering fluid	N/A	Check/top-up
Coolant/heater hoses	N/A	Check/report
Air filter	Check/clean	Renew
Diesel fuel filter	N/A	Renew
Auxiliary drive belt/s	N/A	Check/adjust
Ad-blue	Top-up	Top-up
FINAL ITEMS CHECK		
Vehicle locks/hinges	N/A	Check/lubricate
Headlamp alignment	N/A	Check/adjust
Four point wheel alignment	N/A	Check/adjust
Road wheel nuts/bolts	N/A	Check tightness
ROAD TEST VEHICLE		
Steering free-play	N/A	Check/report
Clutch operation	N/A	Check/report
Vehicle suspension operation	N/A	Check/report
Engine performance	N/A	Check/report
Transmission	N/A	Check/report
Brakes	N/A	Check/report
ABS function	N/A	Check/report
Instruments	N/A	Check/report
AFTER ROAD TEST		
Engine	Check/report	Check/report
Vehicle condition	Check/report	Check/report
TOTAL TIME (hours)	0.9	2.4*
Additional operations on request		
Brake hydraulic fluid - renew	every 100,000 km	1.1
Front differential oil	every 240,000 km	0.3
Rear didderential oil	every 320,000 km	0.5
Engine coolant - renew	every 320,000 km	0.5
Transmission oil - renew	80 000 km	0.3

* 1 hour including Four wheel alignment

*