



Vehicle Technical Inspection Form

ISUZU NPR



Type of car	ISUZU NPR
Type of body	Light Truck
Year of product	2003
Fuel	Diesel
Color	White
Vehicle Chassis No	JAANPR66LY7100035
Mileage	143098 KM
Engine	Good
Suspension	Good
Brakes	Good
Battery	Not Good
Fuel System	Good
Tires	Normal
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of four years!
- Scratches on the left and right side of the cargo body.

Remarks:

- Several minor scratches and dent are visible at the vehicle.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 05.12.2011 at 135 009 KM

Accident history:

- No major body damages.

Required repairs:

- Batteries need to be replaced.





