



Vehicle Technical Inspection Form

NISSAN Pathfinder



Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2009
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVR51Z0349466
Mileage	182 818 KM

Engine	Good
Suspension	Good
Brakes	Good
Battery	Good
Fuel System	Good
Tires	Good
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of four years!
- Paint peeled on the both wheel arches.

Remarks:

- Minor scratches on the rear right door.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 30.09.2013 at 174 400KM
- Vehicle clutch renewed on 16.07.2012 at 132 737 KM

Accident history:

- Front part of the vehicle was damaged and repaired.

Required repairs:



