



Vehicle Technical Inspection Form

NISSAN PATROL



Type of car	NISSAN Patrol
Type of body	4x4 SUV
Year of product	2008
Fuel	Diesel
Color	White
Vehicle Chassis No	JN1TESY61Z0562234
Mileage	144 953 KM
Engine	Good
Suspension	Good
Brakes	Good
Battery	Good
Fuel System	Good
Tires	Good
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of five years!

Remarks:

- All sides of the vehicle slightly scratched.
- Dash Board in bubbles

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 17.10.2013 at 139 921 KM

Accident history:

- No major body damages.

Required repairs:

- Clutch is damaged.



