



## Vehicle Technical Inspection Form

### NISSAN Pathfinder



|                           |                          |
|---------------------------|--------------------------|
| <b>Type of car</b>        | <b>NISSAN Pathfinder</b> |
| <b>Type of body</b>       | <b>4x4 SUV</b>           |
| <b>Year of product</b>    | <b>2009</b>              |
| <b>Fuel</b>               | <b>Diesel</b>            |
| <b>Color</b>              | <b>Blue</b>              |
| <b>Vehicle Chassis No</b> | <b>VSKJVR51Z0347345</b>  |
| <b>Mileage</b>            | <b>166 947 KM</b>        |

|                    |               |
|--------------------|---------------|
| <b>Engine</b>      | <b>Good</b>   |
| <b>Suspension</b>  | <b>Good</b>   |
| <b>Brakes</b>      | <b>Good</b>   |
| <b>Battery</b>     | <b>Good</b>   |
| <b>Fuel System</b> | <b>Good</b>   |
| <b>Tires</b>       | <b>Normal</b> |
| <b>Hand brake</b>  | <b>Good</b>   |

**Visual inspection of vehicle:**

- The vehicle is in reasonable shape and corresponds with the service life of four years!
- Minor scratches on the rear right fender

**Remarks:**

- Rear bumper plastic lost

**Maintenance records:**

- Vehicle has been serviced after each 10,000 km. Last service on 04.06.2013 at 160 680 Km

**Accident history:**

- No major body damages.

**Required repairs:**

- Clutch damaged
- Need new battery.



