



Vehicle Technical Inspection Form

NISSAN Pathfinder



Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2008
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVWR51Z0350184
Mileage	158 486 KM
Engine	Good
Suspension	Good
Brakes	Good
Battery	Not Good
Fuel System	Good
Tires	Good
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of five years!
- Paint peeled on the both wheel arches.
-

Remarks:

- Front bumper right side scratched.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 18.10.2012 at 150 000 KM

Accident history:

- No major body damages.

Required repairs:

- Need new battery.
- Rear Boot Glass broken.
- Generator damaged.
- Pulley Alternator damaged





