

**Vehicle Technical Inspection Form****NISSAN Pathfinder SE**

Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2009
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVWR51Z0350027
Mileage	149 148 KM

Engine	Good
Suspension	Good
Brakes	Good
Battery	Not Good
Fuel System	Good
Tires	Normal
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of five years!
- Major paint peeled on the engine hood.

Remarks:

- Front bumper scratched on the right side.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 01.02.2013 at 140 940 KM
- Vehicle clutch renewed on 29.06.2012 at 111 873 KM

Accident history:

- No major body damages.

Required repairs:

- Need to replace battery.





