



Vehicle Technical Inspection Form

NISSAN Pathfinder EUMM 059



Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2008
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVWR51Z0337783
Mileage	170 645 KM
Engine	Good
Suspension	Good
Brakes	Good
Battery	Not Good
Fuel System	Good
Tires	Normal
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of five years!
- Minor scratches on both side of vehicle

Remarks:

- The front bumper is a bit cuttted with antenna holder

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 08.10.2013 at 155 245 Km

Accident history:

- No major body damages.

Required repairs:

- Need new battery.
- A/C compressor faulty
- Clutch faulty
- Rear shock-absorbers worn-out





