



Vehicle Technical Inspection Form

NISSAN PATROL EUMM 070



Type of car	NISSAN Patrol
Type of body	4x4 SUV
Year of product	2008
Fuel	Diesel
Color	White
Vehicle Chassis No	JN1TESY61Z0562229
Mileage	151 061 KM
Engine	Good
Suspension	Good
Brakes	Good
Battery	Good
Fuel System	Good
Tires	Ok
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of five years!

Remarks:

- Both sides of vehicle are scratched by bushes
- Dash Board in bubbles

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 10.12.2013 at 149 812 km

Accident history:

- No major body damages.

Required repairs:

- Starter damaged.
- Spare tire mount bolts damaged
- A/C System Faulty





