

**Vehicle Technical Inspection Form****NISSAN Pathfinder SE**

Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2009
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVWR51Z0350135
Mileage	177 903 KM
Engine	Good
Suspension	Good
Brakes	Good
Battery	Not Good
Fuel System	Good
Tires	Normal
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of four years!

Remarks:

- Moderate scratches.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 17.02.2014 at 174795 KM
- Vehicle clutch and flywheel renewed on 05.06.2013 at 145350 KM

Accident history:

- No major body damages.

Required repairs:

- Need new battery.



