

**Vehicle Technical Inspection Form****NISSAN Pathfinder SE**

Type of car	NISSAN Pathfinder
Type of body	4x4 SUV
Year of product	2009
Fuel	Diesel
Color	Blue
Vehicle Chassis No	VSKJVWR51Z0350297
Mileage	158 365 KM

Engine	Good
Suspension	Good
Brakes	Good
Battery	Not Good
Fuel System	Good
Tires	Normal
Hand brake	Good

Visual inspection of vehicle:

- The vehicle is in reasonable shape and corresponds with the service life of four years!
- Paint peeled on the front bumper and hood.
-

Remarks:

- Moderate scratches on the right side, on front and rear bumpers.

Maintenance records:

- Vehicle has been serviced after each 10,000 km. Last service on 26.12.2013 at 149870 KM
- Vehicle clutch renewed on 27.06.2013 at 125120 KM

Accident history:

- No major body damages.

Required repairs:

- Need new battery.



